

Fire Department New York Incident Report

Incident Reviewed By

Reviewer 912069 - PAVIS ROBERT E. Battalion Chief
Date 11/22/2020

Incident

Incident # 4-0795-0
Status Closed
Incident Date/Time 11/21/2020 17:56:00
Incident Type 111 - Building fire
Box# 2302
Address 226 E 53 ST 2R Brooklyn
Apartment/Suite 2R
Borough 4 - Brooklyn
Action Taken1 11 - Extinguishment by fire service personnel
Rescued (civilians) 0
Evacuated (civilians) 2
Property Use 429 - Multifamily dwelling

Resources

Unit Responsible for Report: BC41

Unit Type 92 - Chief officer car
Action Taken1 811 - Assigned All Hands Chief
Dispatch Date/Time 11/21/2020 18:04:05
Enroute Date/Time 11/21/2020 18:06:36
Arrival Date/Time 11/21/2020 18:09:21
Cleared Date/Time 11/21/2020 18:40:04
Unit Report By 912069 - PAVIS ROBERT E. Battalion Chief
Narrative
Incident Narrative
Incident number 11/21/2020-4-0795-0
On Saturday, November 21, 2020 at 17:56 hours the following units were dispatched to a report of a building fire. The incident location is street address 226 E 53 ST Apt. 2R Brooklyn NY, 11203.

Primary incident actions taken are as follows:
Actions taken - extinguished

The Times for Incident #11/21/2020-4-0795-0 are as follows:

Unit Responsible for Report: BC41

Signal: Time: By Order Of:
10-75 17:58 B-38 BC Pavis
U.C. 18:58 B-38 BC Pavis
Total Time of Incident - 01:02:26

Upon arrival Units operated as follows:

BC41 arrived at 18:09 hours and cleared at 18:40 hours.
Actions taken - assigned to All Hands Chief

E310 arrived at 17:58 hours and cleared at 18:49 hours.
Actions taken - extinguished, hook line up to hydrant and stretch 1 3/4" line and extinguish fire

E283 arrived at 17:59 hours and cleared at 18:40 hours.
Actions taken - assist engine company with stretching handline and hook line up to hydrant

E234 arrived at 18:03 hours and cleared at 18:38 hours.
Actions taken - stretch precautionary line and then stood fast

L174 arrived at 17:58 hours and cleared at 18:45 hours.
Actions taken - perform primary search of fire area and perform secondary search

L123 arrived at 18:04 hours and cleared at 18:39 hours.
Actions taken - perform secondary search of fire area and perform primary search

BC38 was dispatched at 17:56 hours and cleared at 18:58 hours.
Actions taken - incident command

E248 arrived at 18:08 hours and cleared at 18:56 hours.
Actions taken - fill-in/moveup

L170 arrived at 18:10 hours and cleared at 18:29 hours.
Actions taken - operate/assigned as Fast Unit

DC15 arrived at 18:07 hours and cleared at 18:24 hours.
Actions taken - incident command

RS02 arrived at 18:08 hours and cleared at 18:23 hours.
Actions taken - check extension

RA02 arrived at 18:26 hours and cleared at 18:53 hours.
Actions taken -

AM03 was dispatched at 18:04 hours and cleared at 18:36 hours.
Actions taken - take action other

E252 arrived at 18:13 hours and cleared at 18:19 hours.
Actions taken - checked exposures

Reporting Member: 912069 ROBERT E PAVIS
Unit Responsible: BC41

Fire

Residential Units	1
Cause of Ignition	5 - Cause under investigation
Case	31292
Area Of Origin	24 - Cooking area, kitchen
Heat Source	10 - Heat from powered equipment, other
Item First Ignited	10 - Structural component or finish, other
Condition on Arrival	2 - Smoke only Showing
Factor Contributing To Ignition1	UU - Undetermined
Suppression Factor1	315L - Light clutter – potential to affect operations
Equipment Involved Type	124 - Stove, heating
Equipment Involved Power	20 - Gas fuels, other
Equipment Involved Portability	2 - Stationary
Mobile Property Involved	None

Structure

Structure Type	1 - Enclosed building
Building Type	3 - Non-Fireproof Structure
Building Status	2 - In normal use
Floors Above Grade	2
Floors Belows Grade	1
Building Length	60
Building Width	25
Story of Fire Origin	2
Fire Spread	2 - Confined to room of origin
Building Type	3 - Non-Fireproof Structure
Stand Pipe System Present	No
Detector Presence	N - None present
AES Presence	N - None Present