

# Fire Department New York

## Incident Report

### Incident Reviewed By

Reviewer 908358 - JOYCE CHRISTOPHER J. Battalion Chief  
Date 05/11/2022

### Incident

Incident # 5-0013-0  
Status Closed  
Incident Date/Time 04/14/2022 00:37:46  
Incident Type 111 - Building fire  
Box# 4104  
Address 67-01 FOREST AVE Queens  
Borough 5 - Queens  
Shift 6X  
Action Taken1 11 - Extinguishment by fire service personnel  
Action Taken2 215 - Check for extension  
Action Taken3 216 - Checked exposures  
Rescued (civilians) 0  
Evacuated (civilians) 0  
Property Use 000 - Property Use, other

### Resources

#### Unit Responsible for Report: BC28

Unit Type 92 - Chief officer car  
Action Taken1 81 - Incident command  
Action Taken2 86 - Investigate  
Action Taken3 82 - Notify other agencies.  
Dispatch Date/Time 04/14/2022 00:38:41  
Enroute Date/Time 04/14/2022 00:38:51  
Arrival Date/Time 04/14/2022 00:41:43  
Cleared Date/Time 04/14/2022 03:26:10  
Unit Report By 908358 - JOYCE CHRISTOPHER J. Battalion Chief  
Narrative Incident Narrative  
Incident number 04/14/2022-5-0013-0  
The incident location is street address 67-01 FOREST AVE Queens NY, 11385.

**Unit Responsible for Report: BC28**

Upon arrival Units operated as follows: units arrived on scene to what apparently looked like a roof fire. Upon examination the fire originated in a enclosed shaft between the fire building 67-01 Forest ave (corner building) and exposure 4 67-03 Forest ave at the cellar level. Heavy fire extended into the top floor of 2R in the fire building and 2L in 67-03. initial line line was stretched in fire building and operated into the shaft to extinguish the shaft fire lines were also stretched to the second floor of both building to extinguished fire front to rear in both buildings roof was opened and lines operated at roof level to extinguish fire at that level. All searches complete and negative. Units operated as per CD-15"s

10-75 @00:41:43 All hands 00:44:42 Second alarm at 00:50:04 PWH 01:41:11 U?C 02:00:06

The owner of the building [REDACTED] Buildings representative Mills #1716 Red cross on scene relocated 5 adults and & children from the two apartments

FD had two injured members E-291 Bart Sagan left side. L-112 Raymond Ferrer back and leg

BC28 arrived at 00:41 hours and cleared at 03:26 hours.  
Actions taken - incident command

E277 arrived at 00:41 hours and cleared at 07:19 hours.  
Actions taken -

E277 arrived second due and hooked up to hydrant on Cornelia Street. Members assisted E291 in getting first line into place, then stretched 1 3/4 line from E271 to top floor of fire building. Extinguished fire in front of second floor and washed down interior enclosed shaft from window. Relieved by E206 and went to RAC unit.

E291 arrived at 00:41 hours and cleared at 03:18 hours.  
Actions taken -

Arrived 1st due and operated on 1st floor of main fire building for a shaft fire. Repositioned to exposure 4 cellar to extinguish extension. Repositioned to exposure 3 to extinguish extension.

L112 arrived at 00:41 hours and cleared at 03:23 hours.  
Actions taken -

L112 operated on 2nd floor of 67-01 Forest Ave. L112 was responsible for forcing multiple doors, as well as locating and isolating fire in the apartment . L112 conducted primary searches throughout the 2nd fl as well as secondaries on first floor, basement, and shaft. L112 also overhauled these area extensively .

**Unit Responsible for Report: BC28**

L140 arrived at 00:41 hours and cleared at 02:56 hours.  
Actions taken - operated in the original fire building assisted E-291 with access to fire area. roof operations as well as searches

E271 arrived at 00:41 hours and cleared at 02:47 hours.  
Actions taken -

Engine 271 stretched the second 1 3/4" attack line into the exposure 4 building, extinguishing heavy fire that had extended via the shaft

E286 arrived at 00:41 hours and cleared at 03:05 hours.  
Actions taken -

Q252 arrived at 00:41 hours and cleared at 01:36 hours.  
Actions taken -

Upon arrival ordered to assist with VES of Fire Building and EXP.4.  
Roof FF To roof to assist with Roof Operations.  
Upon completion of all assigned duties ordered back in service.

RS04 arrived at 00:41 hours and cleared at 01:44 hours.  
Actions taken -

Rescue 4 checked in with Batt 28 and then split up the company. Rescue 4 officer, Irons and Hook operated in exp 4. Rescue 4 can operated in the fire building and R4 roof went to the roof. Rescue 4 Chauff searched the basements and shaft openings.

DC14 arrived at 00:42 hours and cleared at 02:29 hours.  
Actions taken - incident command

AM04 arrived at 00:42 hours and cleared at 00:42 hours.  
Actions taken - take action other

RA02 arrived at 00:42 hours and cleared at 03:26 hours.  
Actions taken -

BC37 arrived at 00:42 hours and cleared at 02:37 hours.  
Actions taken -

Operated as Fire Sector Supervisor. Supervised searched for Life and Fire in fire building

L124 arrived at 00:42 hours and cleared at 02:37 hours.  
Actions taken -

L124 inside team operated on the top floor of the fire building performing primary searches and overhauling. L124 Roof assisted in ventilation of the roof. L124 OV operated from the bucket and assisted on the roof. L124 LCC operated from the pedestal and later entered the fire building. We then searched for extension to exp 4A and overhauled the enclosed shaft between the fire building and exp 4 and the enclosed shaft between exp 4 and exp 4A

E218 arrived at 00:45 hours and cleared at 02:54 hours.  
Actions taken -

**Unit Responsible for Report: BC28**

Engine 218 backed up the second line into the fire building. Assisted in packing up all hose lines once under control.

L135 arrived at 00:45 hours and cleared at 02:29 hours.

Actions taken -

L-135 arrived at Box 4104 and was assigned as the FAST Truck. L-135 assembled FAST Unit equipment adjacent to the command post, had the Roof FF monitor the EFAS in the command vehicle.

L-135 monitored HT Tactical channel throughout operation. Irons FF Forced Bilco door of exposure 4. L-135 Chauffeur Laddered the building and was prepared to operate as a TL.

L176 arrived at 00:50 hours and cleared at 02:27 hours.

Actions taken -

L-176 searched for extension of fire in exposure 4. L-176 shut off all utilities and conducted secondaries which came up negative.

TS01 arrived at 00:51 hours and cleared at 02:15 hours.

Actions taken -

E324 arrived at 00:50 hours and cleared at 01:55 hours.

Actions taken -

E324 transported Sat 4, positioned at and tested a hydrant. Members stood fast until released by Incident Commander

ST04 arrived at 00:50 hours and cleared at 01:55 hours.

Actions taken -

Sat 4 staged with associated Engine Co at hydrant, members stood fast until released by Incident Commander

SB01 arrived at 00:51 hours and cleared at 01:47 hours.

Actions taken -

RM01 arrived at 00:53 hours and cleared at 02:28 hours.

Actions taken - take action other

RB01 arrived at 00:51 hours and cleared at 01:46 hours.

Actions taken -

Rescue Battalion assigned to doctors office with E291 to open up for extension and final extinguishment.

FC01 arrived at 00:51 hours and cleared at 01:08 hours.

Actions taken -

FC01 responded on the 2nd alarm. Reported to the command post upon arrival. Monitored all department and HT communications. Assisted Division and resource unit leader with accountability of members at the scene. Maintained the command board. Transmitted progress reports and messages as requested. FC01 was released from the scene when fire was placed Under Control and went 10-8.

**Unit Responsible for Report: BC28**

CT01 arrived at 00:51 hours and cleared at 02:13 hours.  
Actions taken -

BC46 arrived at 00:50 hours and cleared at 03:07 hours.  
Actions taken -

BC44 arrived at 00:50 hours and cleared at 02:05 hours.  
Actions taken -

Operated as Resource Unit Leader. Relieved by DC McBride.

BC35 arrived at 00:50 hours and cleared at 02:16 hours.  
Actions taken -

operated as Bn 35 roof sector supervisor and exposure 4A sector

E233 arrived at 00:50 hours and cleared at 02:09 hours.  
Actions taken -

Stood fast, ordered to return to quarters by FC1

E206 arrived at 00:50 hours and cleared at 03:23 hours.  
Actions taken -

E222 arrived at 00:50 hours and cleared at 03:26 hours.  
Actions taken -

E-222 responded to 2-2 Box 4104 upon arrival E-222 reported to the command post where they were given orders to back-up assist E-291 with their handline. E-222 later was assigned watchline until relieved by E-258.

L154 arrived at 01:10 hours and cleared at 07:19 hours.  
Actions taken -

Ladder 154 responded as additional truck on the 2nd alarm after relocating to the quarters of L140.  
L154 was ordered by command to relieve L140 on the second floor of the fire bldg we did some overhauling until we were relieved

L123 arrived at 01:10 hours and cleared at 02:12 hours.  
Actions taken -

Ladder 154 responded as additional truck on the 2nd alarm after relocating to the quarters of L140.  
L154 was ordered by command to relieve L140 on the second floor of the fire bldg we did some overhauling until we were relieved

Reported to the command Post where we remained. Did Not Operate.

E258 arrived at 02:47 hours and cleared at 07:07 hours.  
Actions taken -

E326 arrived at 05:44 hours and cleared at 07:19 hours.  
Actions taken -

**Unit Responsible for Report: BC28**

E-326 maintained a watch line

Reporting Member: 908358 CHRISTOPHER J JOYCE  
Unit Responsible: BC28**Fire**

Residential Units	1
Buildings Involved	1
Cause of Ignition	5 - Cause under investigation
Case	40381
Area Of Origin	UU - Undetermined
Heat Source	UU - Undetermined
Item First Ignited	UU - Undetermined
Condition on Arrival	3 - Flame and Smoke Showing
Factor Contributing To Ignition1	UU - Undetermined
Suppression Factor1	NNN - None
Equipment Involved In Ignition	None
Mobile Property Involved	None

**Structure**

Structure Type	1 - Enclosed building
Building Type	3 - Non-Fireproof Structure
Building Status	2 - In normal use
Floors Above Grade	2
Floors Belows Grade	1
Building Length	60
Building Width	20
Story of Fire Origin	0
Fire Origin Below Grade	Yes
Fire Spread	5 - Beyond building of origin
Building Type	3 - Non-Fireproof Structure
Stand Pipe System Present	No
Detector Presence	N - None present
AES Presence	N - None Present
Stories Minor Flame	0
Stories Heavy Flame	3
Stories Heavy Smoke	3

<b>Structure</b>	
Stories Heavy Water	3
<b>Fire Service Casualty (2)</b>	
	