

Fire Department New York

Incident Report

Amendments

Amended By 914760 - CARDI CRAIG Battalion Chief 12/07/2021 18:45:18

Incident Reviewed By

Reviewer 914760 - CARDI CRAIG Battalion Chief
Date 12/07/2021

Incident

Incident # 4-0619-0
Status Closed
Incident Date/Time 12/07/2021 17:08:19
Incident Type 100 - Fire, other
Box# 0959
Address 8 ARLINGTON PL Apt: ROOF Fl: ROOF Brooklyn
Apartment/Suite ROOF
Floor ROOF
Borough 4 - Brooklyn
Shift 9X
Action Taken1 11 - Extinguishment by fire service personnel
Action Taken2 21 - Search
Rescued (civilians) 0
Evacuated (civilians) 0
Detector U - Unknown
Property Use 429 - Multifamily dwelling

Resources

Unit Responsible for Report: BC57

Unit Type 92 - Chief officer car
Action Taken1 81 - Incident command
Dispatch Date/Time 12/07/2021 17:08:43
Enroute Date/Time 12/07/2021 17:09:05
Arrival Date/Time 12/07/2021 17:15:41
Cleared Date/Time 12/07/2021 18:02:44
Unit Report By 914760 - CARDI CRAIG Battalion Chief

Unit Responsible for Report: BC57

Narrative

Incident Narrative

Incident number 12/07/2021-4-0619-0

On Tuesday, December 7, 2021 at 17:08 hours the following units were dispatched to a report of a fire. The incident location is street address 8 ARLINGTON PL Apt. ROOF Brooklyn NY, 11216.

Primary incident actions taken are as follows:

Actions taken - extinguished and searching

Upon arrival Units operated as follows: Units arrived to a small fire showing on the roof of 6 Arlington Place and 8 Arlington place. Units caused minor damage in the roof, ceilings on top floor of both houses and the cornice in front of building checking for fire extension. E280 stretched a hoseline to the roof to extinguish the fire on the roof. L111 and L132 reported that there was no fire on the top floor in both apartments. The owner of 6 Arlington place Mr Peter Putka informed BC57 that the building had roofers doing work on the roof earlier in the day. After the fire was out all units took up and Mr Putka was left in charge.

BC57 arrived at 17:15 hours and cleared at 18:02 hours.

Actions taken - incident command

E214 arrived at 17:25 hours and cleared at 18:01 hours.

Actions taken - assist engine company with stretching handline

L132 arrived at 17:13 hours and cleared at 18:14 hours.

Actions taken - perform primary search, perform secondary search and check extension

L111 arrived at 17:12 hours and cleared at 17:55 hours.

Actions taken - perform primary search, perform secondary search and check extension

E280 arrived at 17:12 hours.

Actions taken - stretch 1 3/4" line and extinguish fire and hook line up to hydrant

E219 arrived at 17:13 hours and cleared at 17:56 hours.

Actions taken -

E235 arrived at 17:17 hours and cleared at 18:05 hours.

Actions taken -

AM03 arrived at 17:27 hours and cleared at 17:27 hours.

Actions taken - take action other

BC38 arrived at 17:26 hours and cleared at 17:45 hours.

Actions taken -

DC11 arrived at 17:27 hours and cleared at 17:47 hours.

Actions taken -

L102 arrived at 17:26 hours and cleared at 17:57 hours.

Actions taken -

Unit Responsible for Report: BC57

Q001 arrived at 17:26 hours and cleared at 18:15 hours.
Actions taken -

RA02 arrived at 17:26 hours and cleared at 17:58 hours.
Actions taken -

RS02 arrived at 17:26 hours and cleared at 17:55 hours.
Actions taken -

Reporting Member: 914760 CRAIG CARDI
Unit Responsible: BC57

Fire

Residential Units	1
Buildings Involved	1
Cause of Ignition	5 - Cause under investigation
Case	31338
Area Of Origin	77 - Roof surface: exterior
Heat Source	00 - Heat source: other
Item First Ignited	UU - Undetermined
Condition on Arrival	3 - Flame and Smoke Showing
Factor Contributing To Ignition1	UU - Undetermined
Equipment Involved In Ignition	None
Mobile Property Involved	None