

Fire Department New York Incident Report

Incident Reviewed By

Reviewer 912056 - MINOGUE MICHAEL J. Battalion Chief
Date 08/25/2021

Incident

Incident # 4-1291-0
Status Closed
Incident Date/Time 08/04/2021 18:03:43
Incident Type 100 - Fire, other
Box# 0669
Address 689 MYRTLE AVE 5I Brooklyn
Apartment/Suite 5I
Borough 4 - Brooklyn
Shift 6X
Action Taken1 64 - Shut down system
Action Taken2 42 - HazMat detection, monitoring, sampling, & analysis
Action Taken3 302 - Provide Patient Care
Rescued (civilians) 1
Evacuated (civilians) 40
Detector U - Unknown
Property Use 429 - Multifamily dwelling

Resources

Unit Responsible for Report: BC57

Unit Type 92 - Chief officer car
Action Taken1 81 - Incident command
Dispatch Date/Time 08/04/2021 18:04:15
Enroute Date/Time 08/04/2021 18:04:32
Arrival Date/Time 08/04/2021 18:09:41
Cleared Date/Time 08/04/2021 20:36:05
Unit Report By 912056 - MINOGUE MICHAEL J. Battalion Chief
Narrative Incident Narrative
Incident number 08/04/2021-4-1291-0
On Wednesday, August 4, 2021 at 18:03 hours the following units were dispatched to a report of a fire. The incident location is street address

Unit Responsible for Report: BC57

689 MYRTLE AVE Apt. 5I Brooklyn NY, 11205.

Primary incident actions taken are as follows:

Actions taken - shut down system, material detection, monitoring, sampling, and analysis and provide patient care

Upon arrival Units operated as follows:

BC57 arrived at 18:09 hours and cleared at 20:36 hours.

Actions taken - incident command

Cause under investigation . Appears to have been caused by natural gas due to the residual amount of gas in areas of the fire apartment and the adjoining apartment.

E216 arrived at 18:08 hours and cleared at 18:34 hours.

Actions taken - hook line up to hydrant, material detection, monitoring, sampling, and analysis and investigation

E211 arrived at 18:08 hours.

Actions taken - hook line up to hydrant, stretch precautionary line and then stood fast and investigation

L119 arrived at 18:11 hours and cleared at 19:26 hours.

Actions taken - perform secondary search of fire area, material detection, monitoring, sampling, and analysis, searching and shut down system

L102 arrived at 18:11 hours and cleared at 20:32 hours.

Actions taken - perform primary search, shut down system, ventilation and investigation

E235 arrived at 18:11 hours and cleared at 19:45 hours.

Actions taken - hook line up to hydrant, provide patient care and assist engine company with stretching handline

RS02 arrived at 18:11 hours and cleared at 18:38 hours.

Actions taken - material detection, monitoring, sampling, and analysis, searching and investigation

CT01 arrived at 18:11 hours and cleared at 18:53 hours.

Actions taken - cancelled en route

SC01 arrived at 18:11 hours and cleared at 19:14 hours.

Actions taken -

RC02 arrived at 18:11 hours and cleared at 19:07 hours.

Actions taken -

FC01 arrived at 18:11 hours and cleared at 19:50 hours.

Actions taken - provide manpower

E250 arrived at 18:11 hours.

Actions taken - investigation and material detection, monitoring, sampling, and analysis

Q001 arrived at 18:11 hours and cleared at 19:02 hours.

Actions taken - material detection, monitoring, sampling, and analysis

Unit Responsible for Report: BC57

HM01 arrived at 18:11 hours and cleared at 18:23 hours.
Actions taken -

HB01 arrived at 18:11 hours and cleared at 19:15 hours.
Actions taken - investigation

L132 arrived at 18:11 hours and cleared at 18:40 hours.
Actions taken - material detection, monitoring, sampling, and analysis, searching and investigation

RS04 arrived at 18:11 hours and cleared at 18:26 hours.
Actions taken - investigation

SL01 arrived at 18:12 hours and cleared at 19:14 hours.
Actions taken -

RB01 arrived at 18:12 hours and cleared at 18:34 hours.
Actions taken -

BC35 arrived at 18:19 hours and cleared at 19:15 hours.
Actions taken - assigned to All Hands Chief

RA02 arrived at 18:19 hours and cleared at 20:36 hours.
Actions taken - provide manpower, provide water and provide apparatus

DC11 arrived at 18:19 hours.
Actions taken - incident command

L108 arrived at 18:19 hours and cleared at 19:10 hours.
Actions taken - operate/assigned as Fast Unit

AM03 arrived at 18:19 hours and cleared at 18:19 hours.
Actions taken - take action other

E217 arrived at 18:19 hours and cleared at 18:42 hours.
Actions taken - provide manpower

SB01 arrived at 18:23 hours and cleared at 18:26 hours.
Actions taken - cancelled en route

E279 arrived at 19:08 hours and cleared at 20:49 hours.
Actions taken - code enforcement and investigate

BC35 arrived at 18:19 hours.
Actions taken - assigned to All Hands Chief

Reporting Member: 912056 MICHAEL J MINOGUE
Unit Responsible: BC57

Fire

Residential Units	1
Cause of Ignition	5 - Cause under investigation

Fire

Case	30857
Area Of Origin	24 - Cooking area, kitchen
Heat Source	UU1 - Heat source under investigation
Item First Ignited	UU - Undetermined
Condition on Arrival	1 - No Flame or Smoke Showing
Factor Contributing To Ignition1	23 - Leak or break
Equipment Involved Type	UUU - Undetermined
Equipment Involved Power	UU - Undetermined
Equipment Involved Portability	2 - Stationary
Mobile Property Involved	None

